



FARMBOT

MONITORING SOLUTIONS



LINE PRESSURE SENSOR

INSTALLATION GUIDE

**PLEASE READ ENTIRE GUIDE BEFORE
INSTALLATION**

PROVIDED TOOLS

LINE PRESSURE SENSOR


1/4 INCH BSP MALE FITTING + CABLE



1. INSERT PRESSURE SENSOR INTO PIPE




2. TURN MONITOR OFF




IF THE SWITCH IS NOT VISIBLE PUSH AWAY FROM THE SOLAR PANEL

3. CONNECT THE CABLE TO ANY PORT 1 - 4 OF THE MONITOR



4. TURN MONITOR ON



IF THE SWITCH IS NOT VISIBLE PUSH TOWARDS THE SOLAR PANEL

